

NO  
2020

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

- Name of the Officer
- Name of the School
- Location with name of Education District/ Sub. District
- Classification of Building as specified in column 4 of the application for fitness certificate and size.

Shehara C.A.  
St. Joseph Public School, Theottuva  
Kothamangalam, Perumbavoor.

G.F - Cl-1: 5.98 x 7.48 x 2.6, Cl-2: 5.98 x 7.49 x 3.69  
Cl-3: 5.98 x 7.48 x 3.60, Cl-4: 5.98 x 7.49 x 3.60  
STAFF ROOM: 5.95 x 2.98 x 3.60, Cl-5 (6 to 11): 6.78 x 6.78 x 3.6  
1<sup>st</sup> Floor Lab: 5.98 x 14.95 x 2.60, Library: 5.98 x 7.48 x 3.60  
STAFF ROOM: 6.18 x 5.95 x 3.60, Cl-12: 7.48 x 5.95 x 3.60  
Book store: 7.24 x 5.95 x 3.60, Cl-13: 6.78 x 6.78 x 3.60  
LAB: 6.78 x 10.28 x 3.60 LAB: 6.78 x 10.17 x 3.60  
COMPUTER LAB: 6.78 x 6.67 x 3.60

- Period for which the certificate is issued
- Nature of defects, if any
  - Foundation and basement
  - Superstructure
  - Doors and Windows
  - Wood work wrought and put up
  - Roof
  - Flooring
  - Miscellaneous (Cracks, etc.)
- Any major defects noticed which will render the building unsafe in any manner

: 2020-21

Nil

No  
Yes

Yes the structure is sound under normal climate condition

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 27.05.2020 and found to be fit / ~~unfit~~ to conduct classes, for the period 2020-21 for the reasons stated above.

Place: Koovappady  
Date: 27.05.2020



*[Signature]*  
Assistant Engineer

ASSISTANT ENGINEER  
Local Government Dept.  
Koovappady Section  
Koovappady P.O.